



Nokia X Disassembly Prerequisites


Written By: Jose Maya



 **TOOLS:**


- [Spudger \(1\)](#)

Step 1 — Nokia X Disassembly Prerequisites



- Remove the back cover of the device by applying light pressure toward the outer rim and display.

Step 2



- Remove 7 (size 4 M1 4*3.5) and 4(size 6 M2 6*4.5) screws using P5 hex screwdriver.
- The M2 screws are shown in red.
- The M1 screws are shown in orange.

Step 3



- Gently separate the display from the chassis.
- Slowly spread the display and chassis until the inside of the device is reachable.

 Do not pull apart.

Step 4



- Using the [spudger](#) tool, release the top flex ribbon from the light swap package.

To reassemble your device, follow these instructions in reverse order.