




# OnePlus 3 Interconnect Cable Disconnect

Prerequisite guide only! Steps to disconnect the interconnect cables from the motherboard.

Written By: Arthur Shi




# INTRODUCTION

Prerequisite guide only! Steps to disconnect the interconnect cables from the motherboard.

## TOOLS:

- [Phillips #00 Screwdriver](#) (1)
- [Spudger](#) (1)

## Step 1 — OnePlus 3 Interconnect Cable Disconnect



- Remove the 3 mm Phillips screw securing the cable bracket.
- Remove the cable bracket.

## Step 2



- Use the point of a spudger to pry up and disconnect the interconnect flex cable from the motherboard, which is located above the battery.
- Repeat the process to disconnect the daughterboard flex cable from the motherboard.

To reassemble your device, follow these instructions in reverse order.