



# Philips Infracare HP3621 bulb Replacement

Simply replacing the bulb.

Written By: Joris



## INTRODUCTION

Intercepted this device on its way to the trash, because of a fried bulb that the manufacturer wouldn't replace.

Figured I'd take a look, expecting I would have to buy a fancy bulb to replace the original.

Turned out to be a 3€ fix that I gladly did.

Sharing the very trivial steps to show that it can be done.

### TOOLS:

- [Flathead Screwdriver](#) (1)
- [Phillips #1 Screwdriver](#) (1)

### PARTS:

- [230-240v 200w 118mm halogen bulb](#) (1)

## Step 1 — Remove the stand




- Slide the flathead screwdriver beneath the plastic stand and press slightly to unfasten it.
- Repeat on the other side, then remove the stand.

## Step 2 — Unscrew the back cover



- Use the Philips screwdriver to remove the 4 screws

## Step 3 — Remove the covers



- Gently remove the cover so as not to damage any wiring
- The metal light deflector is not attached to anything, simply remove it to reach the bulb and the next step

## Step 4 — Replace the bulb



- That's it. Nothing fancy here. Remove the bulb by pulling it to one side. Replace with the new one.

To reassemble your device, follow these instructions in reverse order.