



Philips Norelco 5801XL Blade Replacement

Replace damaged or dull shaver blades in your Philips Norelco 5801XL.

Written By: Ben Gibbs



INTRODUCTION

Use this guide to remove the shaver head and replace the blades in the Philips Norelco 5801XL. The blades are sharp, so pay close attention when handling them.



PARTS:



- Norelco HQ5 Replacement Blades (1)

Step 1 — Blade



- Press down on the black button below the shaver head.

Step 2



- Turn the white gear counterclockwise to release the retaining bracket.
- Remove the retaining bracket.

Step 3



- Remove the blades from the shaver head.

To reassemble your device, follow these instructions in reverse order.