



# Replacing the Huawei Nova Plus Screen

Replacing a broken screen on the Huawei Nova Plus.


Written By: Cesar Roman



 **TOOLS:**

- [Phillips #0 Screwdriver \(1\)](#)
- [T2 Torx Screwdriver \(1\)](#)
- [iFixit Opening Picks set of 6 \(1\)](#)
- [iFixit Opening Tools \(1\)](#)
- [Heat Gun \(1\)](#)

## Step 1 — Screen




- Before starting, extract the SIM tray.

## Step 2



- Torx #2
- Pry in between the screen and the back cover. All electronic components are on the back of the screen.

## Step 3



- Disconnect the fingerprint reader.

## Step 4



- Remove the battery, lower PCB and screen connector bracket. Use a Philips #0 screwdriver.
- Screen connector

## Step 5



ⓘ Connect and test the new screen before assembling it.

## Step 6



- Philips #0
- Disconnect speaker
- Remove speaker

## Step 7



*(i)* Apply heat on the top and bottom of the screen until it can be removed with the prying tools. Remove as much adhesive as possible and assemble the new screen.

Follow these instructions in reverse order to reassemble your device.