



Saeco Vienna Sup 018 water tank seal replacement

Replacement of the water tank seal on a Saeco Vienna Sup 018

Written By: VauWeh



INTRODUCTION

If the water tank drips when it is not installed in the machine, then the water tank seal needs to be replaced. This simple repair will be demonstrate hier. If the water tank loses water while it is inserted in the coffee machine, then the water tank seal in the unit needs to replaced. This is shown [here](#)

TOOLS:

- Metal Spudger (1)

PARTS:

- New Item (1)

Step 1 — Water tank seal



- Lift the water tank off the machine

Step 2



- With your fingers pull the filter off the water outlet.

Step 3



- With your fingers press the valve stem from the bottom up. Now you can pry off the seal with a spatula tip.

To reassemble your device, follow these instructions in reverse order.