



The refrigerator will not cool sufficiently

Replace the evaporator fan and flash (upgrade) the controller microcode

Written By: Michael Williams

INTRODUCTION

Contact GE Customer relations and ask for part #WR49X25197 . They will send a new evaporator fan and a small box that will easily allow you to upgrade the microcode

TOOLS:

- [Phillips 2 Screwdriver, 1/4" drive socket set \(1\)](#)

PARTS:

- [part #WR49X25197 \(1\)](#)

Step 1 — Contact GE 800 432 2737



- Insert wisdom here.

Step 2 — With parts in hand watch this video which shows how to do this



- Insert wisdom here.- <https://www.youtube.com/watch?v=EqyIQnRZ...>

Step 3 — Follow instructions for installing microcode



- RJ 45 plugs into a receptacle on the top of the unit. It is towards the front.

Step 4 — Send back microcode installation module



- Insert wisdom here.

To reassemble your device, follow these instructions in reverse order.