



# URPOWER V2 Ultrasonic Aroma Essential Diffuser Fan Replacement

Removing and replacing the Coolcox CC5010M12S fan in UrPower Oil Diffuser.

Written By: Lilian Kay



## INTRODUCTION

If your URPOWER V2 Ultrasonic Aroma Essential Diffuser is making a buzzing noise, use this guide to replace the Coolcox CC5010M12S fan. The fan can have a faulty blade that creates a buzzing noise when on.

Before beginning make sure there is no water in the device.

### **TOOLS:**


- [Magnetic Project Mat \(1\)](#)
- [Phillips #00 Screwdriver \(1\)](#)

## Step 1 — fan




- Unplug the Oil Diffuser.

## Step 2



- Using a Phillips #00 screwdriver from the iFixit kit, remove all three 10.0 mm screws on the bottom piece.



## Step 3



- Remove the bottom piece of the Oil Diffuser.


*(i)* Be careful not to lose the outside light and air buttons.

## Step 4




- Unplug the fan power cord.

## Step 5



- Using the Phillips #00, remove two 10.0 mm screws holding the fan onto the base of the diffuser.

## Step 6



- Remove and replace the fan.

To reassemble your device, follow these instructions in reverse order.