




Why iPhone X Face ID not work after repairing

If your Face ID not work after repairing, watch this video you can find why this happen.

Written By: Mandy



INTRODUCTION

The infrared camera and dot projector as the main parts of Face ID system are tied to the unique logic board inside each iPhone X.

The flood illuminator works with the Face ID system and is tied to the unique logic board inside each iPhone X, so it failed after replacing.

More details about the conclusion please visit <https://www.etradesupply.com/blog/can-ip...>

TOOLS:

- Suction Handle (1)
- P2 Pentalobe Screwdriver iPhone (1)
- Spudger (1)
- Tri-point Y000 Screwdriver Bit (1)
- Tweezers (1)
- iFixit Opening Picks set of 6 (1)
- Metal Spudger (1)
- Large Needle Nose Pliers (1)
- Heat Gun (1)
- Phillips PH000 Screwdriver (1)
- iFixit Opening Tools (1)
- Microfiber Cleaning Cloths (1)
- Soldering Iron (1)

