# Microsoft Band 2 Battery Replacement

Removing the Microsoft Band 2 battery

Written By: Chris Syracuse

INTRODUCTION

This guide will show you how to remove the Microsoft Band 2 battery in case the battery dies out, a common problem in the Band 2.

TOOLS:

- T3 Torx Screwdriver (1)
- Metal Spudger (1)
- iFixit Opening Tools (1)
- Tweezers (1)

PARTS:

- Microsoft Band 2 Replacement Battery (1)

This document was generated on 2019-09-18 08:46:35 AM (MST).

Step 1 — Battery

- Peel back the metal cover on the end of the watchband.

Step 2

- Use a T3 Torx screwdriver to unscrew the four 6 mm screws on the corners of the metal cover plate.

This document was generated on 2019-09-18 08:46:35 AM (MST).

Step 3

- Use the plastic opening tool to pry off the metal cover plate.

Step 4

- Detach the black ribbon cable by using the tweezers.

Step 5

- Detach the orange press-fit (or "pop") connector by using the tweezers.

Step 6

- Pry out the battery using the plastic opening tool.

To reassemble your device, follow these instructions in reverse order.

This document was generated on 2019-09-18 08:46:35 AM (MST).