



BK Technical Forum

Original Topic Posted on 4/7/2011
by Gary Kessler

[Post a Reply](#)

Topic : DPH "Group 99" fix

Communication issues with some serial-to-USB adapters may result in DPHX radios being able to select non-existent channel groups such as "Group 99".

A patch to resolve this occurrence can be downloaded from the BK firmware section.

NOTE: THIS ISSUE DOES NOT AFFECT RADIO OPERATION IN GROUPS 1-25.