

Prepared (Subject resp) XMRDMFI Dmitry Filyushin		No. 17/1543-ANA 901 37 Uen		
Approved (Document resp) BDGSGHDD [Hans Fernqvist]	Checked	Date 2018-05-07	Rev C	Reference

SS7 CAF Link Deactivated

Contents

1	Overview	2
1.1	Description	2
2	Procedure	2

Prepared (Subject resp) XMRDMFI Dmitry Filyushin		No. 17/1543-ANA 901 37 Uen		
Approved (Document resp) BDGSGHDD [Hans Fernqvist]	Checked	Date 2018-05-07	Rev C	Reference

1 Overview

Note: This alarm is deprecated.

1.1 Description

The alarm is issued when a signaling link has been deactivated by an operator to make it unavailable for traffic.

Major type	193
Minor type	1586562568
MO Class	N/A
Specific Problem	SS7 CAF Link Deactivated
Severity	SEVERITY_MINOR
Additional Text	Link Deactivated

The possible causes are as follows:

- An operator sent link deactivation order for the specific link. The active ECM was moved due to the user request.

2 Procedure

Link may be reactivated by operator intervention. If the alarm is raised without any preceding actions contact the next level of maintenance support, see SS7 CAF Troubleshooting Guide for details.