

Prepared (Subject resp) XMRDMFI Dmitry Filyushin		No. 24/1543-ANA 901 37 Uen		
Approved (Document resp) BDGSGHDD [Hans Fernqvist]	Checked	Date 2018-05-16	Rev C	Reference

SS7 CAF SCTP IP Path is Down

Contents

1	Overview	2
1.1	Description	2
2	Procedure	2

Prepared (Subject resp) XMRDMFI Dmitry Filyushin		No. 24/1543-ANA 901 37 Uen		
Approved (Document resp) BDGSGHDD [Hans Fernqvist]	Checked	Date 2018-05-16	Rev C	Reference

1 Overview

Note: This alarm is deprecated.

1.1 Description

The alarm is issued when one of the SCTP IP paths has become inactive.

Major type	193
Minor type	1586601228
MO Class	N/A
Specific Problem	SS7 CAF Sctp IP Path Is Down
Severity	SEVERITY_WARNING
Additional Text	Sctp IP Path Is Down

The possible causes are as follows:

- An SCTP IP Path became inactive/unavailable/unreachable.

2 Procedure

Normally this is a non-fatal alarm; SCTP will use other paths in the association for communicating with the remote peer. SCTP will automatically make new attempts to make this IP path available.

If the alarm is persistent contact the next level of maintenance support, see SS7 CAF Troubleshooting Guide for details.