

Prepared (Subject resp) XNATTOL Nataliya Tolokontseva		No. 22/1543-ANA 901 37 Uen		
Approved (Document resp) BICPAGCB [Hans Fernqvist]	Checked	Date 2016-11-23	Rev B	Reference

**SS7 CAF DPC State Change**

**Contents**

1	Overview	2
1.1	Description	2
2	Procedure	2

Prepared (Subject resp) XNATTOL Nataliya Tolokontseva		No. 22/1543-ANA 901 37 Uen		
Approved (Document resp) BICPAGCB [Hans Fernqvist]	Checked	Date 2016-11-23	Rev B	Reference

## 1 Overview

### 1.1 Description

The alarm is issued when the status of the destination point has changed.

Major type	193
Minor type	1586564139
MO Class	N/A
Specific Problem	SS7 CAF DPC State Change
Severity	SEVERITY_MINOR
Additional Text	DPC State Change

The possible causes are as follows:

- The remote SPC became unreachable/unavailable.
- Congestion was detected.

## 2 Procedure

This notification does not require any remedial actions. To get details on the cause of the alarm see SS7 CAF trace file. Additional information about SS7 CAF trace file can be found in SS7 CAF Troubleshooting Guide.