

Labelling of Cables

Company Confidential

NUMBER OF BAG	SPECIFIC USE	CODE	SIZE	COLOUR	QUANTITY
1 EARTHING CABLES	Main Earthing 25 mm ²	1000	10×40	black	2
	(Site Earthing Busbar 25 mm ²)	1001	10×40	black	2
	Feeder Earthing 25 mm ²	1002	10×40	black	2
	BBU or SSS Earthing, + pole	1003	10×40	black	2
	Spare	1004	10×40	black	2
	BBU or SSS Earthing 16 mm ²	1005	10×40	black	2
	MDF/DDF Earthing 4-16 mm ²	1006	10×40	black	2
	Transmission Earthing 16 mm ²	1007	10×40	black	2
	Spare	1008	10×40	black	2
	Spare	1009	10×40	black	2
	BTS, Earthing of Basic Cabin 16 mm ²	1110	10×40	black	2
2 AC SUPPLY CABLES	BTS, Earthing of Extension Cabin 16 mm ²	1120	10×40	black	2
	AC Main Supply	2000	10×40	black	2
	1st Rectifier Supply Cable	2001	10×40	black	2
	2nd Rectifier Supply Cable	2002	10×40	black	2
	Spare	2003	10×40	black	2
	Spare	2004	10×40	black	2
	Spare	2005	10×40	black	2
	DC Cables of 1st Battery String	3000	10×40	black	2
	DC Cables of 2nd Battery String	3001	10×40	black	2
	DC Cables of 3rd Battery String	3002	10×40	black	2
	DC Cables of 4th Battery String	3003	10×40	black	2
3 DC SUPPLY CABLES	PSA, Transmission Supply	3004	10×40	black	2
	Spare	3005	10×40	black	2
	Spare	3006	10×40	black	2
	DC Supply for BTS-Rack	3110	10×40	black	2
	Redundant DC Supply for BTS-Rack	3111	10×40	black	2
	DC Supply for BTS-Extension Rack	3120	10×40	black	2
	Redundant DC Supply for BTS-Ext. Rack	3121	10×40	black	2

4	RF CABLES	STM Feeder	4000	22x50	black	2
		RX/TX 1st MW-Link Feeder	4010	10x40	black	2
		RX/TX 2nd MW-Link Feeder	4011	10x40	black	2
		RX/TX 3rd MW-Link Feeder	4020	10x40	black	2
		RX/TX 4th MW-Link Feeder	4021	10x40	black	2
		Spare	4030	10x40	black	2
		Spare	4031	10x40	black	2
		Spare	4040	10x40	black	2
		Spare	4041	10x40	black	2
		1st Sector TX/RX Feeder	4110	22x50	white	2
		1st Sector RXd Feeder	4111	22x50	white	2
		2nd Sector TX/RX Feeder	4120	22x50	Red	2
		2nd Sector RXd Feeder	4121	22x50	Red	2
		3rd Sector TX/RX Feeder	4130	22x50	Blu	2
		3rd Sector RXd Feeder	4131	22x50	Blu	2
		4rd Sector TX/RX Feeder	4140	22x50	Black	2
		4rd Sector RXd Feeder	4141	22x50	Black	2
		5rd Sector TX/RX Feeder	4150	22x50	Black	2
		5rd Sector RXd Feeder	4151	22x50	Black	2
		6rd Sector TX/RX Feeder	4160	22x50	Black	2
		6rd Sector RXd Feeder	4161	22x50	Black	2
5	PCM CABLES	TRU1 O & M / Q1_1	5000	10x40	Black	2
		RX/TX 1 120Ω (TQ connector)	5110	10x40	Black	2
		RX/TX 2 120Ω	5111	10x40	Black	2
		RX/TX 3 120Ω	5120	10x40	Black	2
		RX/TX 4 120Ω	5121	10x40	Black	2
		RX 1 75Ω (BT43 connector)	5130	10x40	Black	2
		TX 1 75Ω	5131	10x40	Black	2
		RX 2 75Ω	5140	10x40	Black	2
		TX 2 75Ω	5141	10x40	Black	2
		RX 3 75Ω	5150	10x40	Black	2
			5151	10x40	Black	2
			5150	10x40	Black	2
			5151	10x40	Black	2
			5150	10x40	Black	2
			5151	10x40	Black	2

NUMBER OF BAG	SPECIFIC USE	CODE	SIZE	COLOUR	QUANTITY
6 ALARM CABLES	BBU monitoring	6000	10x40	black	2
	External Alarm	6001	10x40	black	2
	External Alarm	6002	10x40	black	2
	External Alarm	6003	10x40	black	2
	External Alarm	6004	10x40	black	2
	External Alarm	6005	10x40	black	2
	External Alarm	6006	10x40	black	2
	External Alarm	6007	10x40	black	2
	External Alarm	6008	10x40	black	2
	External Alarm	6009	10x40	black	2
	Customer Controls 0-5 and Alarms 0-11	6110	10x40	black	2
	Customer Alarms 12-23	6120	10x40	black	2
	Support Alarms	6130	10x40	black	2

CABLE TIES:

2,4 x 92 mm black 300 pcs
4,8 x 186 mm black 50 pcs