

Business Radio CPS R09.05 Customer Release Notes

If you have any questions, please reach out to Motorola Solutions help desk at 1-800-448-6686.

I. <u>Enhancements</u>

Supports 11 digit serial number change for the CLS and DTR radios

II. <u>Model Numbers Affected</u>

CLS1110 CLS1410 CLS1413 CLS1810 DTR700

III. CPS

New CLS and DTR series radios will require Business Radio CPS R09.05 for programming purposes due to the serial number change. R09.05 CPS is in MyView to download.

MOTOROLA SOLUTIONS and the Stylized M Logo are registered in the U.S. Patent & Trademark Office. All other product or service names are the property of their respective owners. © Motorola Solutions, Inc. 2014.