

KS-21118 HEAD TELEPHONE SETS

DESCRIPTION, USE, AND MAINTENANCE

1. GENERAL

1.001 This addendum supplements Section 028-352-501, Issue 2. Place this pink sheet ahead of Page 1 of this section.

1.002 This addendum is issued for the following reasons:

- (1) To rate the KS-21118 Head Telephone Sets and all replacement parts Mfr Disc.
- (2) To change copyright notice on the bottom of Page 1.

The Equipment Test List is not affected.

2. CHANGES TO SECTION

2.001 On the bottom of Page 1, delete the copyright notice and add the following:

NOTICE

Not for use or disclosure outside the
Bell System except under written agreement

2.002 On Page 1, paragraph 1.01, add the following note:

Note: Replacement parts are no longer available and Western Electric cannot repair the KS-21118 head telephone sets. As trouble occurs on any KS-21118 head telephone sets, remove from service and dispose of them in accordance with local procedures.

NOTICE

Not for use or disclosure outside the
Bell System except under written agreement