

CALCULAGRAPHS
MODELS 6 AND 30 AND KS-7769 (MODEL 33)
OPERATING METHODS

1. GENERAL

1.001 This addendum supplements Section 030-100-301, Issue 1. Place this pink sheet ahead of Page 1 of the section.

1.002 This addendum is issued to change note following paragraph 3.29. This addendum does not affect the Equipment Test List.

2. CHANGES TO SECTION

2.001 On Page 5, change note following paragraph 3.29 to read as follows:

Note: To operate the motor-alternator without load, the "A" relay in the 24-volt supply leads to the motor must be manually blocked non-operated.

NOTICE

Not for use or disclosure outside the
Bell System except under written agreement