

**1-TYPE MESSAGE TICKETER**  
**PIECE-PART DATA AND REPLACEMENT PROCEDURES**

**1. GENERAL**

**1.001** This addendum supplements Section 030-360-801, Issue 1. The attached pages must be inserted in Section in accordance with filing instruction.

**1.002** This addendum is issued to add two piece-part numbers to Fig. 6.

**2. PIECE-PART DATA**

The following changes apply to Part 2 of this section.

- (a) Fig. 6—Piece-part TP-101629, Feed Pawl, added.
- (b) Fig. 6—Piece-part TP-101637, Spacer Pawl, added.

**Attached:**

**Page 3 dated February 1971, Reissued**

**Page 4 dated February 1971, Revised**




Fig. 3—Motor (without external thrust bracket)




Fig. 4—Motor (with external thrust bracket) (earlier model)




Fig. 5—Printing Mechanism (top view)




Fig. 6—Printing Mechanism (bottom view)




Fig. 7—Cutter Blade and Tape Guide