



MAGNETIC TAPE MANAGEMENT

1. GENERAL

1.001 This addendum supplements Section 034-311-301, Issue 1. The attached pages must be inserted in the section in accordance with the filing instructions above.

1.002 This addendum is issued to provide instructions for the following:

- That the magnetic tape surfaces should not be permitted to come in contact with the floor
- That each new reel of tape be full width certified at 3200 FCI (1600 BPI) with a minimum detection level of 35% at final inspection.

2. TAPE HANDLING

The following change applies to Part 2 of this section:

- (a) 2.01(e)—revised.

7. VERIFICATION OF TAPE QUALITY

The following change applies to Part 7 of this section:

- (a) 7.01—revised.

9. TAPE PROCUREMENT REQUIREMENT

The following change applies to Part 9 of this section:

- (a) 9.01—revised.

Attached:

Page 1 dated June 1974, revised
Page 2 dated June 1974, reissued
Page 13 dated June 1974, reissued
Page 14 dated June 1974, revised
Page 15 dated June 1974, revised
Page 16 dated June 1974, reissued