

RESISTOR—CAPACITOR TIMED RELAY INTERRUPTER TESTS

1. GENERAL

- 1.001** This addendum supplements Section 040-009-501, Issue 2.
- 1.002** This addendum is issued to revise 2.06.

2. CHANGE TO SECTION

ISSUE 1 CHANGE

- 2.001** On Page 1, change 2.06 pulse checking test set, J94725 to J94723.