

**REPLACING PAGE ADDENDUM**

**Filing Instructions:**

1. REMOVE FROM THE SECTION THE PAGES NUMBERED THE SAME AS THOSE ATTACHED TO THIS PINK SHEET.
2. INSERT THE ATTACHED PAGES INTO THE SECTION IN THEIR PLACE.
3. PLACE THIS PINK SHEET AHEAD OF PAGE 1 OF THE SECTION.

**RELAYS**

**111 (PART OF 163), 121, 122, 125, 149, 162, 178, AND 179 TYPES**

**PIECE-PART DATA AND REPLACEMENT PROCEDURES**

**1. GENERAL**

**1.001** This addendum supplements Section 040-219-801, Issue 4. The attached pages must be inserted in the section in accordance with the filing instructions above.

**1.002** This addendum is issued to delete the piece-part information from the Table of Variable Parts and the Table of Contact Insulators and Contact Spring Studs for the 125A, 125F, 125G, 125K, 125M, 125R, 125S, 125AC, 125AD,

125AF, 125AH, 125AJ, and 125AN relays, all of which have been rated Manufacture Discontinued.

**2. PIECE-PART DATA**

The following changes apply to Part 2 of this section:

- (a) Table of Variable Parts—revised
- (b) Table of Contact Insulators and Contact Spring Studs—revised.

**Attached:**

**Page 7 dated September 1973, revised**  
**Page 8 dated September 1973, revised**  
**Page 13 dated September 1973, revised**  
**Page 14 dated September 1973, reissued**