

209-TYPE RELAY
AND
ASSOCIATED 18-TYPE CONNECTING BLOCKS
PIECE-PART DATA AND REPLACEMENT PROCEDURES

1. GENERAL

1.001 This addendum supplements Section 040-231-801, Issue 3.

1.002 This addendum is issued to change the piece-part number of a washer used on

the terminal block, Fig. 5. Present piece-part number of washer is P-213287.

The new piece-part number for this washer is P-284192.