

## EQUIPMENT TEST LIST TRANSMISSION TEST EQUIPMENT

### 1. GENERAL

1.001 This addendum supplements Section 103-001-011, Issue 11.

1.002 It is reissued to:

- Change the "J" numbers on Cosine Equalizer.
- Establish an ETS routine maintenance time interval for the model TTS-95 Reference Tone Generator (See Exhibit 1.)
- Establish an ETS routine for a J 94007A (7A) carrier frequency noise measuring set.
- Include the appropriate legend on Page 1 in accordance with AT&T's "Guidelines and Procedures for Safeguarding Information" and Pacific Company's System Instruction (SI) 178.

*Note:* Marginal arrows used to denote changes are omitted.

### 2.14 TRMSN TST EQPT; MISCELLANEOUS

The following change applies to Part 2.14 of the section:

- J68839A & J68839B CONSINE EQUALIZER — Change to J68837A & J68837C COSINE EQUALIZER.

### 2.15 TRMSN TST EQPT; MISC CONT.

The following change applies to Part 2.15 of the section:

- J68839A & J68839B COSINE EQUALIZER RECEIVER MAINTENANCE — Change to J68837A & J68837C COSINE EQUALIZER RECEIVER MAINTENANCE.

Exhibit 1 — added

#### NOTICE

Not for use or disclosure outside the  
Bell System except under written agreement

