

KS-5654-01 AC-DC MOTOR-ALTERNATORS REPLACEMENT PARTS AND PROCEDURES

1. GENERAL

1.001 This addendum supplements Section 155-108-801, Issue 1. Place this pink sheet ahead of page 1 of the section.

1.002 This addendum is issued to change the first sentence in 3.09 (b) to read: "With the R-1542 adjustable wrench applied to the two flats provided at the outboard end of the shaft, turn the armature shaft in a *counterclockwise* direction as viewed from the exciter end."