

INTERTOLL DIALING
TYPE B CX AND SX SIGNALING CIRCUITS
OVERALL DIALING TRUNK PULSING TEST FROM TOLL TESTBOARDS

1. GENERAL

1.001 This addendum supplements Section 179-708-507, Issue 1. Place this pink sheet ahead of Page 1 of this section.

1.002 This addendum is issued for the following reasons:

- (a) To change 3P6F cord to 3P14B cord on Page 7
- (b) To change pulse test patch circuit to pulse test jack circuit on Page 11

(c) To change a step reference from 92 to 91 on Page 16.

2. CHANGES TO SECTION

2.001 On Page 7, Step 53, change 3P6F to 3P14B.

2.002 On Page 11, Step 117, change patch to jack.

2.003 On Page 16, Step 108l, change 92 to 91.

NOTICE

Not for use or disclosure outside the
Bell System except under written agreement