

List S.T. # 149 Date MAY 2 1968

AMA ACCURACY AND ROUTE VERIFICATION TESTS

NO. 4A AND 4M TOLL SWITCHING SYSTEMS

1. GENERAL

1.001 This addendum supplements Section 212-700-900PT, Issue A.

1.002 This addendum is issued to:

- (a) Change a form number.
- (b) Provide flexibility in scheduling tests for AMA tape entries.
- (c) Provide AMA accuracy and route verification procedures for changes associated with existing codes.
- (d) Revise the procedure for verifying the integrity of "DJ" leads.

1.003 Form E-4104 is replaced by Form E-4104PT. Section 034-310-301PT, Appendix 1 describes how to use Form E-4104PT.

The following change applies to Part 1 of the Section:

- (a) 1.03 (a) - added note

1.03 (a) (Add at the end of this subparagraph.)

NOTE: The above interval can be changed with approval of the T&A Committee.

2. ESTABLISHING NEW TERMINATING CODES OR CHANGING EXISTING TERMINATING CODES IN EXISTING RECORDER GROUPS

The following change applies to Part 2 of the Section:

- (a) 2. - revised.

2. ESTABLISHING NEW TERMINATING CODES OR CHANGES ASSOCIATED WITH EXISTING CODES

9. INSTALLING INCOMING CAMA TRUNKS AND OUTGOING TRUNKS TO NEW AND EXISTING RECORDER GROUPS

The following change applies to Part 9 of the Section:

- (a) 9.02 - revised

9.02 Verify the integrity of the "DJ" lead on each incoming CAMA trunk installed. Use the procedures outlined in 7.12 through 7.17 of this section, with the exception of 7.13.

NOTE: To avoid billing a customer, the number passed to the CAMA operator must not be assigned to a customer.