

LINE VERIFICATION TESTS
USING MASTER TEST FRAME
NO. 5 CROSSBAR OFFICES ARRANGED
FOR PBX DIAL TRANSFER

1. GENERAL

1.01 This section provides information for making line verification tests of lines and trunks appearing in the Extra Number group for Private Branch Exchange (PBX) Dial Transfer services.

1.02 It is reissued to:

- Update the format to conform to Pacific Bell's standards.
- Include the appropriate legend on Page 1 in accordance with System Instruction (SI) 178.

Note: Marginal arrows used to denote changes are omitted.

1.03 All extra number group line verification tests are made in a standard manner per Section 218-102-501 except for the following:

- (a) Operate IC-OA or OB key for all tests.
- (b) Operate TT switch on Trunk Test Circuit to ENLT.
- (c) Operate A9, B-, C-, D- keys corresponding to the tie line or trunk number.

1.04 If a trouble record card is dropped there will be no A- digit punched because the marker is directed to the extra number group by the ENLT key rather than a thousand digit. CMA punch indicates MLV-Match and NO Sleeve Check. CMB punch indicates PBX Line Busy. CMC punch indicates MLV-Match and Sleeve Check.

NOTICE

Not for use or disclosure outside Pacific Bell/
Nevada Bell except under written agreement