

TROUBLE AND FUSE ALARMS  
MISCELLANEOUS CIRCUITS  
OPERATION TESTS  
355A COMMUNITY DIAL OFFICES

1. GENERAL

1.001 This addendum supplements Section 225-345-500.

1.002 It is issued to rate the 1011-type dial hand test set (handset) nonstandard for Pacific Company (PAC) use.

1.003 The 1011-type handset is replaced by the 1013- or 1014-type handset. These approved handsets are equipped with varistors which limit possible loud tones or signals received to sound pressure levels below the Occupational Safety and Health Act specified maximum. Information on these handsets is contained in Sections 100-120-101 and 106-020-113.

NOTICE

Not for use or disclosure outside the  
Bell System except under written agreement

Printed in U.S.A.