

**LINE FINDERS — WITHOUT CONTROL CIRCUIT**  
**OPERATION TESTS**  
**USING DIAL HAND TEST SET**  
**STEP-BY-STEP SYSTEMS**

**1. GENERAL**

**1.001** This addendum supplements Section 226-200-500, Issue 1.

**1.002** It is issued to inform the tester of possible delays in line finder release time (Test A) when the line finder is associated with the **TELONE\*** M-911-16 Coin-Free Trunk Adapter (Section 226-521-900PT).

**4. METHOD**

The following changes apply to Part 4 (Test A) of the section:

- Step 3 (Verification) — revised

**STEP 3 (Verification)** — Each idle line finder in turn, beginning with No. 1 or 11, steps vertically to proper level, cuts in, rotates to eleventh rotary step, and releases. Where **TELONE** M-911-16 Coin-Free Adapters are associated with line finders to be tested, the line finder release *may* be delayed 3 or 4 seconds.

\* *Registered trademark of TELTONE Corporation*

**NOTICE**

Not for use or disclosure outside the  
Bell System except under written agreement

Printed in U.S.A.