

“TOUCH-TONE®”
CALLING DETECTOR TEST CIRCUIT SD-2H131-01
TESTS AND ADJUSTMENTS
NO. 2 AND NO. 2B ELECTRONIC SWITCHING SYSTEMS

1. GENERAL

1.001 This addendum supplements Section 232-136-501, Issue 3. Place this pink sheet ahead of Page 1 of the section.

1.002 This addendum is issued to include changes due to the EF-2 and 2B-EF-2 generic programs. This addendum does not affect the Equipment Test List.

2. CHANGES TO SECTION

2.001 On page 1, add the following paragraph:

1.02.1 New (conventional) service order codes were adopted for use with the EF-2 and 2B-EF-2 generic programs. However, the translations can be configured with the old (no. 2 ESS unique) service order codes as an option. These old codes are common to all previous No. 2 and No. 2B ESS generic programs. The EF-2 and 2B-EF-2 generic programs can be arranged to recognize either option. In this section the term “conventional (new)” or “No. 2 ESS unique (old)” is used to identify the

service order code for the keyboards in each TTY input message given.

2.002 On page 2, paragraph 3.02, before system response, add the following:

The system response for offices using No. 2 ESS unique (old) code is as follows:

2.003 On page 3, paragraph 3.02, after the system response and before the explanation of the variable fields, add the following:

The system response for offices using conventional (new) code is as follows:

AR VY SVC aaa bbb
OE nn gcsl
PDB cxyzb
. .
DSP ss rrb
. .
END

NOTICE

Not for use or disclosure outside the
Bell System except under written agreement