

COIN CONTROL CIRCUIT (SD-2H125)
WITH DIAL TONE FIRST FEATURES—TESTS
NO. 2 AND NO. 2B ELECTRONIC SWITCHING SYSTEMS

1. GENERAL

1.001 This addendum supplements Section 232-142-501, Issue 2. Place this pink sheet ahead of Page 1 of the section.

DSP ss rrb

1.002 This addendum is issued to include changes due to the EF-2 and 2B-EF-2 generic programs and provide a technical change since the last issue. This addendum does not affect the Equipment Test List.

The system response for offices using conventional (new) code is as follows:

2. CHANGES TO SECTION

AR VY SVC aaa bbb
OE nn gcsl

2.001 On Page 1, add the following paragraph:

1.02.1 New (conventional) service order codes were adopted for use with the EF-2 and 2B-EF-2 generic programs. However, the translations can be configured with the old (No. 2 ESS unique) service order codes as an option. These old codes are common to all previous No. 2 and No. 2B ESS generic programs. The EF-2 and 2B-EF-2 generic programs can be arranged to recognize either option. In this section the term "conventional (new)" or "No. 2 ESS unique (old)" is used to identify the service order code for the keywords in each TTY input message given.

DSP ss rrb

2.003 On Page 3, Step 8, for No. 2B ESS offices, change ss = Number of trunk scanner in decimal (0-11) to ss = Number of trunk scanner in decimal (00-11 for offices using 2B-EF-1 generic program) or (00-30 for offices using 2B-EF-2 generic program).

2.002 On Page 2, paragraph 3.02 change the system response to read as follows:

2.004 On Page 6, Test A, Step 12, delete the information in the action column and add the following:

Operate BAT & GRD C.O. key.

The system response for offices using No. 2 ESS unique (old) code is as follows:

AR VY SVC aaa bbb
TEN nn gcsl

NOTICE

Not for use or disclosure outside the
Bell System except under written agreement