

DIMENSION ® PBX  
FEATURE TEST  
CONTROLLED RESTRICTION ON GROUPS OF LINES

CONTENTS

1. GENERAL
2. RECORD
3. TEST EQUIPMENT
4. DOCUMENT
5. PREPARATION
6. PROCEDURE

---

1. GENERAL

- 1.1 This section provides information to test the controlled restriction on groups of lines.
- 1.2 Perform this feature test only if the stations have been assigned by the factory to control restriction group(s). See Control Restriction Group Assignments section of the COD for the assignment.
- 1.3 An attendant console can activate restrictions on a group of lines by dialing the following format:

CONT REST-GRP DAC + RESTRICTION TYPE + CONT. REST. GRP. NO.

GLOSSARY

CONT REST - GRP DAC - Controlled restriction, on a group of lines, dial access code (It is specified in Trunk and Feature Summary section of COD).

PRIVATE

THE INFORMATION CONTAINED HEREIN SHOULD NOT BE DISCLOSED TO UNAUTHORIZED PERSONS. IT IS MEANT SOLELY FOR USE BY AUTHORIZED BELL SYSTEM EMPLOYEES. Printed in U.S.A.

RESTRICTION TYPE - - See Table A

TABLE A

<u>RESTRICTION TYPE</u>	<u>DESCRIPTION</u>
1 ✓	Outward Restriction
2	Station-To-Station Restriction
3	Outward and Station-To-Station Restriction
4 ✓	Total Restriction
5 ✓	Termination Restriction
6 ✓	Outward and Termination Restriction
0 ✓	Cancel Restriction

CONT. REST. GRP. NO. - Controlled Restriction Group Number (01 through 63). See Controlled Restriction Group Assignments section of COD.

1.4 MAAP feature type 28 is used for the controlled restriction on group of lines feature.

2 RECORD

2.1 Form SD-97-1313 is required for recording the results of this test.

3. TEST EQUIPMENT

<u>QTY.</u>	<u>CODE</u>	<u>DESCRIPTION</u>
1	ITE-4208A	Telephone Hand Set (or 1 - 2500 type telephone set and 1 - 249A adapter).
1	ITE-9153L	Cord Assembly
1	ITE-5735	Trunk Test Set, PBX

4. DOCUMENT

4.1 COD - Customer Order Document

5. PREPARATION

5.1 Connect the ITE-5735, Trunk Test Set, to two CO trunks (one for incoming and one for outgoing). All other CO trunks in that CO trunk group should be busied-out.

5.2 Place one console in manned condition.

138 CRG

6. PROCEDURE

- 6.01 At the console, select an idle loop.
- 6.02 Depress the START key.
- 6.021 Verify that dial tone is heard.
- 6.03 Dial the CONT REST - GRP DAC.
- 6.031 Verify that dial tone is removed at the console.
- 6.04 Dial one of the RESTRICTION TYPES (start with outward restriction = digit 1; and see TABLE A for each type of restriction).
- 6.041 Verify that second dial tone is heard at the console.
- 6.05 Dial a CONT. REST. GRP. NO. (digits 01 through 63; see Controlled Restriction Group Assignments of COD).
- 6.051 Verify that confirmation tone (recall dial tone) is heard at the console.
- 6.06 At the console, release the loop by depressing the RELEASE key.
- 6.07 Connect a telephone set to one station of the restricted group at the test points of line circuit pack.
- 6.08 Test the station and verify that it is being restricted. Each restriction is explained below. Use Test Line for the second station where two stations are required.

<u>TYPE OF RESTRICTION</u>	<u>EXPLANATION</u>
Outward restriction	Restrict group of stations from making CO calls.
→ Station-to-Station Restriction	Restrict groups of stations from receiving station-to-station (intercom) calls.
→ Outward and Station-To-Station Restriction	Restrict group of stations from making CO and receiving Station-to-Station (intercom) calls.
Total Restriction	Restrict group of stations from originating and receiving any calls.
→ Termination Restriction	Restrict group of stations from receiving any calls.
Outward and Termination Restriction	Restrict group of stations from making CO calls and receiving any calls.

6.09 Cancel the restriction on the control restricted group from the console by dialing in the following format:

CONT REST-GRP DAC + 0 (zero) + CONT. REST. GRP. NO.

- 6.091 At the console, select an idle loop and depress the START key.
- 6.0911 Verify that dial tone is heard at the console.
- 6.092 Dial the CONT REST - GRP DAC.
- 6.0921 Verify that dial tone is removed from the console.
- 6.093 Dial digit 0 (zero).
- 6.0931 Verify that second dial tone is heard at the console.
- 6.094 Dial the CONT. REST. GRP. NO. (control restricted group number).
- 6.0941 Verify that confirmation tone (recall dial tone) is heard at the console.
- 6.095 At the console, release the loop by depressing the RELEASE key.
- 6.10 Verify that the restricted station is no longer restricted.
- 6.11 Repeat steps 6.01 through 6.10 for each type of restrictions (1 through 6) as indicated in TABLE A. Perform this feature test once on one station line.

→ Indicates new or changed information.  
Reason for reissue:  
Update Paragraph 6.08

Manager, Denver PBX PECC