

Installation Engineering Handbook 282
 Western Electric
 Denver Works
 DR-4

T of C
 October 30, 1981
 Replacing: T of C
 Dated 7-31-81

DIMENSION^R PBX
 INSTALLATION AND TEST OF
 AUXILIARY EQUIPMENT, AND FEATURE TESTS

TABLE OF CONTENTS

Listed below are the contents of this handbook as of the above date. Check the handbook against this list and order any missing sections. Initial, date and file this Table of Contents in front of this handbook.

Handbooks 3, 100, 250, 218, 218B and 281 are required to supplement information in this handbook.

Refer to Handbook 3, Section 71, for Special Test Precautions for Electronic Devices.

All inquiries pertaining to the contents of this handbook should be directed to the appropriate Regional Installation Engineering Organization contact listed in Installation Engineering Handbook 3 (General Information, Section 0).

<u>Section</u>	<u>Date</u>	<u>Subject</u>
1	10-05-79 ✓	Planning Section
250	10-05-79 ✓	Mounting, Wiring and Cabling of Auxiliary Equipment
250.01	7-15-77 ✓	Night Console
250.02	7-15-77 ✓	Emergency Transfer Panel
250.03	7-15-77 ✓	Customer Premises Facility Terminal (CPFT)
250.04	10-05-79 ✓	Loudspeaker Paging
250.05	7-15-77 ✓	Recorded Telephone Dictation
250.06	7-15-77 ✓	Traffic Measurement Connections (724A Panel)
250.07	7-15-77 ✓	Recorded Announcement
250.08	7-15-77 ✓	Music on Hold
250.09	7-15-77 ✓	DCTS (DIMENSION Custom Telephone Service) Cross Connections
250.10	3-15-78 ✓	Station Message Detail Recordings (SMDR) Connection
250.11	7-01-81 ✓	Remote Maintenance Administration and Traffic System (RMATS) Connection
250.12	7-15-77 ✓	Mounting, Wiring and Cabling of 102C1-A, 102D1-A, 102E1-A Units and Printer
250.18	7-15-77 ✓	120A Frequency Generator (J58879PC-2, L4)
250.19	7-15-77 ✓	Frequency Interrupter (J58879PC-1, L3)
→ 250.20	7-01-81 ✓	Dimension@ PBX Channel Repeater Connection
→ 250.21	7-01-81 ✓	Dimension@ PBX Backup Line Extension Cross Connect
250.22	10-15-81 ✓	30A8 System Status Indicator Cross Connection
→ 250.23	10-05-79 ✓	Code Calling (Chime Paging) Cross Connection
250.25	7-01-81 ✓	Dimension@ PBX Automatic Wakeup Service Audichron Cross Connection and Recording Instructions
→ 250.26	10-15-81 ✓	Dimension@ PBX Energy Communication Service (ECS) Connections

Printed in U.S.A.

PRIVATE

THE INFORMATION CONTAINED HEREIN SHOULD NOT BE DISCLOSED TO UNAUTHORIZED PERSONS. IT IS MEANT SOLELY FOR USE BY AUTHORIZED BELL SYSTEM EMPLOYEES.

<u>Section</u>	<u>Date</u>	<u>Subject</u>
250.27	5-08-81	Extended Memory Holdover Battery Installation and Cross Connections
250.28	10-05-79 ✓	Journal Printers
250.29	10-05-79 ✓	Local Call Billing and Message Register Service Cross Connection on LC16B
250.30	10-05-79 ✓	Interface for Long Distance Billing Connection for Feature Package No. 9
→ 250.31	10-15-81 ✓	Dimension@ PBX Property Management Systems (PMS) Interface Connections
250.32	10-15-81 ✓	Peripheral Interface Circuit (PIC) Cross Connection
250.33	10-05-79 ✓	Radio Paging Cross Connection
1000	10-05-79 ✓	Feature Tests
1010	7-15-77 ✓	Automatic Callback-Calling
1020	7-15-77 ✓	Call Forwarding-All Calls
1030	7-15-77 ✓	Call Forwarding-Busy and Don't Answer
1040	7-15-77 ✓	Call Hold
1050	7-15-77 ✓	Call Pick Up
1060	7-15-77 ✓	Code Restriction
1065	7-15-77 ✓	DID and CCSA Call Restriction
1070	7-15-77 ✓	Custom Intercom
1080	7-15-77 ✓	Executive Override
1090	7-15-77 ✓	Inward Restriction
1100	7-15-77 ✓	Line Lockout with Warning
1110	7-15-77 ✓	Miscellaneous Trunk Restriction Tests
1120	7-15-77 ✓	Originating Restriction
1130	7-15-77 ✓	Outward Restriction
1140	7-15-77 ✓	Speed Calling
1150	7-15-77 ✓	Station Hunting
1160	7-15-77 ✓	Terminating Restriction
1170	7-15-77 ✓	Three-Way Conference Transfer
1410	7-15-77 ✓	Alphanumeric and Class of Service Display

<u>Section</u>	<u>Date</u>	<u>Subject</u>
1420	7-15-77 ✓	Attendant Six-Way Conference
1430	7-15-77 ✓	Attendant Control Trunk Group Access
1440	7-15-77 ✓	Attendant Transfer-All Calls
1450	7-15-77 ✓	Busy Verification of Station Lines
1460	3-15-78 ✓	Controlled Restriction on Groups of Lines
1470	3-15-78 ✓	Controlled Restriction on Single Line
1480	7-15-77 ✓	Direct Trunk Group Selection
1485	7-15-77 ✓	Interposition Calling and Transfer
1490	7-15-77 ✓	Privacy and Lockout
1500	7-15-77 ✓	Splitting-1-Way Automanual
1510	7-15-77 ✓	Timed Recall on Outgoing Trunk
1520	7-15-77 ✓	Timed Reminders
1530	7-15-77 ✓	Trunk Group Busy and Trunk Group Warning Indicators
1540	7-15-77 ✓	Trunk Verification by Customer
1550	7-15-77 ✓	2-Party Hold/Serial Calling
1710	7-15-77 ✓	Automatic Route Select (ARS)
1720	7-15-77 ✓	Call Waiting Services
1721	7-15-77 ✓	Data Line Restriction
1722	7-15-77 ✓	Data Line Privacy
1730	7-15-77 ✓	Fully Restricted Station
1740	7-15-77 ✓	Intercept Treatment
1750	7-15-77 ✓	Manual Terminating Line Service
1760	7-15-77 ✓	Night Service
1770	7-15-77 ✓	Outgoing Trunk Queuing
1780	7-15-77 ✓	Remote Access to PBX Services
1790	7-15-77 ✓	Remote Access Traffic Studies (R.A.T.S.)

<u>Section</u>	<u>Date</u>	<u>Subject</u>
1800	7-15-77 ✓	Route Advance
1810	7-15-77 ✓	Toll Restriction
1820	7-15-77 ✓	Toll Terminal Access
1830	7-15-77 ✓	TOUCH-TONE@ To Dial Pulse Conversion
1840	7-15-77 ✓	Trunk to Trunk Connections
3040	7-15-77 ✓	Test Message Waiting (LC03) - Control by Console
3041	7-15-77 ✓	Test Message Waiting (LC03) - Control by Inquiry/Display Terminal, 102E1 - A Display Unit
3055	7-15-77 ✓	Hot Line Service
3070	7-15-77 ✓	Manual Originating Line Service
5000	7-15-77 ✓	DCTS Feature Test Procedures
5030	7-15-77 ✓	Abbreviated and Delayed Ringing
5040	7-15-77 ✓	Bridged Call
5060	7-15-77 ✓	Dial Intercom
5070	7-15-77 ✓	Hold Control Feature
5110	7-15-77 ✓	Last Station Dialed
5120	7-15-77 ✓	Manual Exclusion
5130	7-15-77 ✓	Manual Intercom
5140	7-15-77 ✓	Manual Signaling
5145	7-15-77 ✓	Station Message Waiting
5160	7-15-77 ✓	Automatic Line Preference
5161	7-15-77 ✓	Idle Line Preference
5162	7-15-77 ✓	Last Line Preference
5163	7-15-77 ✓	No Line Preference
5164	7-15-77 ✓	Prime Line Preference
5165	7-15-77 ✓	Ringling Line Preference

<u>Section</u>	<u>Date</u>	<u>Subject</u>
5166	7-15-77 ✓	Incoming Call Preference
5220	7-15-77 ✓	Recall
5230	7-15-77 ✓	Ringer Cutoff, Enable and Transfer
5240	7-15-77 ✓	Station Busy Indication
5250	7-15-77 ✓	Station DSS
9000	5-08-81	Hotel/Motel Console/Terminal Feature
9010	5-08-81	Hotel/Motel Console/Terminal Alarms
9020	5-08-81	Hotel/Motel and Hospital Console/Terminal Opcodes
9030	5-08-81	Hotel/Motel (or Hospital) Console/Terminal Function Keys
9100	10-05-79 ✓	Automatic Station Restriction for Feature Package No. 9
9110	5-08-81	Automatic Wakeup Service Test-Fixed and Variable
9200	10-05-79 ✓	Calling Number Display to Station (102D1-A)
9210	5-08-81	Flexible Numbering of Stations - Mixed Numbering and Single Digit Dialing
9230	10-05-79 ✓	Housekeeping Extension for Feature Package No. 9
9240	10-05-79 ✓	Message Waiting for Feature Package No. 9
9300	10-05-79 ✓	Local Call Billing for Feature Package No. 9
9310	10-05-79 ✓	Interface for Long Distance Billing Test for Feature Package No. 9
9315	10-05-79 ✓	Room Status and Selection
9400	5-08-81	Feature Test - Energy Communications Service (ECS)
9420	10-05-79 ✓	Split Access to Outgoing Trunks
9500	5-08-81	Extended Memory Holdover Test
→ 80310	7-01-81 ✓	Dimension@ PBX 30A8 CAS System Status Indicator Test
85080	10-05-79 ✓	Automatic Identified Outward Dialing (AIOD)
→ 85105	7-01-81 ✓	Dimension@ PBX Backup Line Extension Test
85255	10-05-79 ✓	Code Calling (Chime Paging) Tests

<u>Section</u>	<u>Date</u>	<u>Subject</u>
85425	10-05-79 ✓	Test Emergency Transfer
86155	10-05-79 ✓	Loudspeaker Paging Tests
86280	10-05-79 ✓	Music on Hold
86705	10-05-79 ✓	Radio Paging Test
86710	10-05-79 ✓	Recorded Announcement Tests
86715	10-05-79 ✓	Recorded Telephone Dictation Tests

Sections required to complete this handbook may be ordered according to local practice or from:

Indiana Publication Center
 Western Electric
 P. O. Box 26205
 Indianapolis, Indiana 46226
 CORNET: 358-3358 Commercial 317-265-3358

→ Indicates new or changed information.

REASON FOR REISSUE:

- Section 250.11 Updated
- Section 250.20 New
- Section 250.21 New
- Section 350.22 Updated
- Section 250.25 New
- Section 250.26 New
- Section 250.31 New
- Section 250.32 Updated
- Section 80310 New
- Section 85105 New

Manager, Denver PBX PECC

Date Checked 2-11-82

Checked By JRA