

GENERAL DESCRIPTION
LOSS COMPONENT
TRUNK TRANSMISSION MAINTENANCE MEASUREMENT PLANS
TRANSMISSION PERFORMANCE MEASUREMENT PLANS

1. GENERAL

1.001 This addendum supplements Section 301-121-100, Issue 2. Place this pink sheet ahead of Page 1 of the section.

1.002 This addendum is issued for the following reasons:

- (a) To change section title to reflect current titling requirements.
- (b) To change paragraph 2.02, Group 2.

2. CHANGES TO SECTION

2.001 On Page 1, change the wording of the section title to the title shown on this addendum.

2.002 On Page 1, paragraph 2.02, Group 2, change to read:

Group 2—Trunks equipped with “E” type or metallic facility terminal (MFT) type repeaters should be measured at least every six months.

NOTICE

Not for use or disclosure outside the
Bell System except under written agreement

Printed in U.S.A.