

24V4B TELEPHONE REPEATER

1.001 This addendum supplements Section 332-104-102, Issue 2.

1.002 It is reissued to:

- Update the format to comply with Pacific Company (PAC) standards
- Include the appropriate legend on Page 1 in accordance with AT&T's "Guidelines and Procedures for Safeguarding Information" and PAC's System Instruction (SI) 178.

1.003 It provides a caution note on the setting of the "S1" screw-down type adjustment, located on the face plate of the 1-type terminating sets.

1. GENERAL.

The following change applies to Part 1 of the section.

- 1.03 — added *Caution*.

1.03 (Add after the last sentence)

CAUTION: When using two-way tie trunk equipment of the SD-65718-01 or SD-66799-01 type, the "S1" adjustment on the 1-type terminating sets should be in the "out" or "open" position. If the "S1" is in the "closed" or "in" position, it will shunt out the 2 db switch pad associated with the trunk equipment.

NOTICE

Not for use or disclosure outside the
Bell System except under written agreement

Printed in U.S.A.