

**TYPE O-H AND ON-H CARRIER TELEPHONE SYSTEMS—
TERMINALS AND JUNCTIONS
SUMMARY CHARTS—LINEUP, MAINTENANCE, AND TROUBLESHOOTING**

1. GENERAL

1.001 This addendum supplements section 362-110-510, Issue 1. Place this pink sheet ahead of Page 1 of the section.

1.002 This addendum is issued to provide surge protection information. This addendum affects the Equipment Test List.

2. CHANGES TO SECTION

2.001 On Page 1, after paragraph 1.06 add the following:

1.07 O-H and ON-H carrier terminals and junctions should be equipped with surge protection per Section 362-105-504 (J98705AA, L40 and L41; SD-95174-01).

NOTICE

Not for use or disclosure outside the
Bell System except under written agreement