

**VOICE CONNECTING ARRANGEMENT STC**  
**KS-20721 STATION COUPLER**

**1. GENERAL**

**1.001** This addendum supplements Section 463-340-103, Issue 2.

**1.002** This addendum is issued to revise paragraph 2.04, rate the KS-20721, List 11 pulse corrector MD, and remove all references to the List 11 and option (V).

**2. CHANGES TO SECTION**

**2.001** On page 2, revise paragraph 2.04 to read as follows:

Under present percent break requirements, the List 11 pulse corrector is not required. The pulse corrector has therefore been rated Manufacture Discontinued (MD) and should not be installed with VCA STC.

**NOTICE**

Not for use or disclosure outside the  
Bell System except under written agreement