

PROTECTIVE CONNECTING ARRANGEMENTS RCZ, RTT, AND RT1, AND 4-WIRE SERVICE

1. GENERAL

1.001 This addendum supplements Section 463-340-120, Issue 5. Place this pink sheet ahead of page 1 of the section.

1.002 This addendum is issued to:

- Clarify information on option Z—used with KS-19645 recorder connectors modified for 4-wire service
- Revise Table C.

(g) All units modified per BSRS 455.205 for 4-wire service have option Z installed which is required when the recorder connector is associated with a line where there is no dc line current. If the unit is to be used on a line where dc line current is present, the telephone company installer can remove option Z by cutting the two red straps located near the OH relay. The OH relay is located just above and to the right of screw terminals C2 and C7. Position the cut ends so there will be no interference with circuit board components.

2. CHANGES TO SECTION

2.001 On page 9 after subparagraph (f), add subparagraph (g) as follows:

2.002 On page 15, Table C is obsolete. A new Table C is shown in this addendum.

NOTICE

Not for use or disclosure outside the
Bell System except under written agreement