

FUNCTION CONTACT ADJUSTMENT

APPARATUS AFFECTED: All 28-Type Typing Units and Sequence Selectors and all 35-Type Typing Units.

OBJECT: To assure proper operation of the front stuntbox contact when the function lever operates the contact arm.

CHANGE: The function contact requirement (2) as shown in Section 573-115-700, issue 5, page 68; Section 573-132-700, issue 3, page 24; and Section 574-220-700, issue 4, page 64 is changed from "not less than 0.008 inch" to min. 0.008 inch, max. 0.028 inch clearance between the formed-over end of the front contact clip and the bottom of the contact arm when the rear contact is closed.

CLASSIFICATION FOR APPARATUS FURNISHED BY TELETYPE: This change is now in effect.

APPLICATION TO APPARATUS IN THE FIELD: The new requirement should be used.

APPLICATION AT W.E.CO. DIST. HOUSE REPAIR SHOPS: The new requirement shall be used.