

## **TP150838 RETAINING RING**

*APPARATUS AFFECTED:* All 28- and 35-type Typing Units.

*OBJECT:* To add another slot for cable routing in order to accommodate the 150 WPM typing unit when it enters production.

*CHANGE:* The TP150838 retaining ring on the spacing drum is changed by adding an additional slot similar to the two existing slots. This slot shall be opposite the two existing slots and midway between the two holes in the retaining ring.

The TP150838 retaining ring is shown in Bulletins 1149B, page 3-24, change 10; and 1187B, page 4-17, original.

*IDENTIFICATION:* See "CHANGE".

*INTERCHANGEABILITY:* Old and new style retaining rings are interchangeable.

*CLASSIFICATION FOR APPARATUS FURNISHED BY TELETYPE:* This change will be made as soon as manufacturing conditions permit.

*W.E.CO. STOCK OF OLD STYLE PARTS:* May be furnished.

*APPLICATION TO APPARATUS IN THE FIELD:* It is not practicable to apply new style parts in the field.

*APPLICATION AT W.E.CO. DIST. HOUSE REPAIR SHOPS:* Units may be equipped with old or new style parts.