

TP193973 TAPE GUARD

APPARATUS AFFECTED: All Typing Reperforator Units; 28H Reperforator Unit; All 28 Reperforator-Transmitter Units; 28A, 28B, 28D, 28E, 28F, 28G, 28G-1, 28H, 28J, 28J-1 and 28K Perforator-Transmitter-Bases; 35A Typing Reperforator Unit; 35AK Typing Reperforator Set; TP193988, TP193989, TP193992, TP193993 Modification Kits on Slack Tape Mechanisms.

OBJECT: To provide additional adjustment margin when positioning the tape guard.

CHANGE: The mounting hole at the end of the long projection on the TP193973 tape guard is increased from 0.191 inch to 0.250 inch diameter. Because of the increased size of the mounting hole, the TP7002 flat washer (0.312 inch diameter) is replaced by a TP125015 flat washer (0.375 inch diameter). The TP193973 tape guard (or platform) is shown in Teletype Specification 50247S, Issue 1, Figures 1 and 2.

IDENTIFICATION: See "CHANGE".

INTERCHANGEABILITY: New style and old style parts are interchangeable.

CLASSIFICATION FOR APPARATUS FURNISHED BY TELETYPE: This change shall be incorporated as soon as manufacturing conditions permit. This is expected to be about December 31, 1964.

W.E.CO. STOCK OF OLD STYLE PARTS: May be used.

APPLICATION TO APPARATUS IN THE FIELD: New style parts should be incorporated if required to meet specified adjustments.

APPLICATION AT W.E.CO. DIST. HOUSE REPAIR SHOPS: The units may be equipped with new or old style parts.