

BELL SYSTEM PRACTICES
Plant Series

Appendix 1, Section 573-137-800, Issue 1
Teletypewriter Change Notice
TCN 919 Issue 1
December, 1967
AT&T Co Standard

Classification: A

Billable to Telco: Yes _____ No X

APPARATUS AFFECTED: 28A and 28B Mounting and Cover Assembly
35A Line Controller (Receiving Selector Base With Motor)
35A and 35B Converter-Selector

PART AFFECTED: None

REASON: To provide an insulating cover for the A. C. power terminals.

CHANGE: A TP321325 connector cover is added to the bases and slip fits over the TP114467 or TP304916 power connector plug.

PUBLICATION AFFECTED: Section 573-137-800, Issue 1, Page 2.

IDENTIFICATION: The TP321325 connector cover is a cone shaped cover 1-7/8 inch long and is made of black rubber. The three wire leads terminating at the power plug are inserted through a small hole in the funnel end of the cover.

INTERCHANGEABILITY: Not affected.

PARTS AVAILABILITY: The TP321325 connector cover is available in limited quantities.

SUPPLEMENTAL INFORMATION: None

REFERENCES: None

TCN INDEX CLASSIFICATION: 28 AH 25
35 AH 25