

PARTS CHANGE

APPARATUS AFFECTED: 33C, 33C-1, 33C-2, 33C-3, 33C-4, 33F, 33F-1, 33F-2, 33F-3, 33F-4 Teletype-writer-Sets.

OBJECT: To facilitate manufacture by eliminating superfluous parts.

CHANGE: The two TP7002 flat washers and one TP124177 lockwasher used on each of the six TP181244 screws to fasten the TP182921 cover to the cabinet are being eliminated.

The TP7002 flat washers, TP124177 lockwasher and TP181244 screws are shown in Teletype Bulletin 1184B, page 5-2, change 3.

IDENTIFICATION: Not involved.

INTERCHANGEABILITY: Not involved.

CLASSIFICATION FOR APPARATUS FURNISHED BY TELETYPE: This change is now in effect.

W.E.CO. STOCK OF OLD STYLE PARTS: The TP7002 flat washers and TP124177 lockwasher may be furnished for other applications.

APPLICATION TO APPARATUS IN THE FIELD: There is no advantage to making this change.

APPLICATION AT W.E.CO. DIST. HOUSE REPAIR SHOPS: Units may be equipped with or without the TP7002 flat washers and TP124177 lockwasher.