

TP181460 PLATE

APPARATUS AFFECTED: 33A, 33A-1, 33A-2, 33A-3, 33A-4, 33B, 33C, 33C-1, 33C-2, 33C-3, 33C-4, 33D, 33D-1, 33D-2, 33D-3, 33D-4, 33E, 33F, 33F-1, 33F-2, 33F-3, and 33F-4 Teletypewriter-Sets.

OBJECT: To make accessible a slot in the TP180783 function casting (in the function box mechanism) for an additional contact block. This slot was formerly blocked by a portion of the TP181460 plate.

CHANGE: The TP181460 plate has been redesigned by:

- (a) Increasing the length from approximately 1-33/64 inch to 1-39/64 inch and increasing the width from approximately 1/2 inch to 45/64 inch.
- (b) Eliminating one of the two 4-40 tapped mounting holes.
- (c) Relocating the existing 4-40 tapped mounting hole.
- (d) Adding two formed projections 1/8 inch wide and 5/32 inch long.

Note: One of the two 4-40 screws, flat washers and lock washers (used for mounting the old style plate) should be discarded when mounting the new plate to the TP180783 casting.

The parts are shown in Bulletin 1184B, page 2-30, change 3.

IDENTIFICATION: See "CHANGE".

INTERCHANGEABILITY: New and old style plates are interchangeable.

CLASSIFICATION FOR APPARATUS FURNISHED BY TELETYPE: This change is now in effect.

W.E.CO. STOCK OF OLD STYLE PARTS: Should not be used.

APPLICATION TO APPARATUS IN THE FIELD: Where required, the new plate should be used.

APPLICATION AT W.E.CO. DIST. HOUSE REPAIR SHOPS: A new style plate shall be used when:

- (a) An additional slot is required for a contact block.
- (or)
- (b) An old style plate requires replacement.

AVAILABILITY: Now available.