

TP182917 SPRING

APPARATUS AFFECTED: 33C-1 to 33C-5 and 33F-1 to 33F-5 Teletypewriter-Sets.

OBJECT: To provide a visible indication of the perforator control buttons in the "ON" (operated) or "OFF" (unoperated) position.

CHANGE: The TP182917 spring has been modified by

1. shortening, by 0.031 inch, two of the four extensions which contact the perforator "ON" and "OFF" TP182919 control buttons.
2. eliminating the 0.0200 formed radius from the two shortened extensions.

The TP182917 spring is shown in Teletype Bulletin 1184B, page 5-2, change 3.

IDENTIFICATION: See "CHANGE".

INTERCHANGEABILITY: New and old style springs are interchangeable. New style springs require assembly with the shorter spring extensions engaging the "ON" and the "OFF" buttons.

CLASSIFICATION FOR APPARATUS FURNISHED BY TELETYPE: This change is now in effect.

W.E.CO. STOCK OF OLD STYLE PARTS: Should not be furnished after new style parts become available.

APPLICATION TO APPARATUS IN THE FIELD: Where desired, the new spring may be used.

APPLICATION AT W.E.CO. DIST. HOUSE REPAIR SHOPS: All units shall be equipped with the new style spring as soon as it becomes available.