

**35A TYPING REPERFORATOR UNIT AND
35A TAPE TYPING UNIT**

APPARATUS AFFECTED: 35A Typing Reperforator Unit and 35A Tape Typing Unit.

OBJECT: To provide a mechanism to suppress printing on codes with #6 and #7 pulse both marking or both spacing.

CHANGE: The TP194236 print suppress modification kit has been added to the 35A typing reperforator unit and the 35A tape typing unit. The TP97117 red-black ribbon is replaced by the TP7835 black ribbon. This modification kit is covered by Specification 50162S. Refer to Bulletin 1188B, page 2-21, and Section 574-231-700, Par. 2.41.

IDENTIFICATION: See "CHANGE".

INTERCHANGEABILITY: Old style and new style units are interchangeable by adding or removing the modification kit.

CLASSIFICATION FOR APPARATUS FURNISHED BY TELETYPE: This change is now in effect.

W.E.CO. STOCK OF OLD STYLE PARTS: Not affected.

APPLICATION TO APPARATUS IN THE FIELD: Modification may be applied, where required for proper operation.

APPLICATION AT W.E.CO. DIST. HOUSE REPAIR SHOPS: All units requiring print suppress feature should be equipped with the TP194236 modification kit.

AVAILABILITY: Now available.