

## **TP151152 SCREW AND TP2034 FLAT WASHER**

*APPARATUS AFFECTED:* 35A Typing Reperforator Unit; 35A, 35B Tape Typing Units; 35A, 35B, 35D Perforator-Transmitter-Bases.

*OBJECT:* To eliminate a possible interference between the TP152893 screw and the TP170124 lubricator assembly.

*CHANGE:* The TP152893 screw and TP150411 flat washer used to fasten the TP156387 trip lever to the TP156388 adjusting arm are replaced by the TP151152 screw and TP2034 flat washer, respectively.

The TP152893 screw and TP150411 flat washer are shown in Teletype Bulletins 1187B, page 5-6, original; 1188B, page 2-2, original.

*IDENTIFICATION:* TP151152 screws are 3/16 inch long; TP152893 screws are 1/4 inch long. TP2034 flat washers are 1/4 inch in diameter; TP150411 flat washers are 3/8 inch in diameter.

*INTERCHANGEABILITY:* TP151152 screws and TP2034 flat washers are interchangeable with TP152893 screws and TP150411 flat washers.

*CLASSIFICATION FOR APPARATUS FURNISHED BY TELETYPE:* This change is now in effect.

*W.E.CO. STOCK OF OLD STYLE PARTS:* May be furnished for other applications.

*APPLICATION TO APPARATUS IN THE FIELD:* Should be incorporated in all apparatus where interference is encountered.

*APPLICATION AT W.E.CO. DIST. HOUSE REPAIR SHOPS:* All units shall be equipped with TP151152 screws and TP2034 flat washers if interference is encountered.

*AVAILABILITY:* Now available.