

File in Handbook RS-581, Book 36B

Classification: A1
Billable to Telco: Yes X No _____

APPARATUS AFFECTED: All DATASPEED 40 Tractor Feed Printers (80- and 132-Column).
TP402570 Form-out Assembly.

PART AFFECTED: TP402571 through TP402580
Form-out Belts.

REASON FOR REISSUE: To change classification from B1C to A1.

REASON: To provide improved form-out belts (by reducing stiffness and belt set) for increased form-out mechanism operating margin.

CHANGE: The material of the TP402571 through TP402580 form-out belts is changed from polyurethane w/ glass fiber to polyurethane without glass fiber.

PUBLICATION AFFECTED: See SUPPLEMENTAL INFORMATION

IDENTIFICATION: Old-style form-out belts are stiffer than new-style due to the glass fiber content.
New-style form-out belts are more resilient and pliable.

There is no color code change associated with this material change, i.e., old- and new-style TP402571 belts are amber, old- and new-style TP402572 belts are blue, old- and new-style TP402573 belts are yellow, etc.

INTERCHANGEABILITY: New-style TP402571, TP402572, TP402573, TP402574, TP402575, TP402576, TP402577, TP402578, TP402579 and TP402580 form-out belts are interchangeable with old-style TP402571, TP402572, TP402573, TP402574, TP402575, TP402576, TP402577, TP402578, TP402579 and TP402580 form-out belts, respectively.

PARTS AVAILABILITY: New-style belts are available on a normal ordering basis.

SUPPLEMENTAL INFORMATION: The TRACTOR FEED FORM-OUT BELT SELECTION chart is illustrated in the following publications:

Section 582-200-101, Issue 1, Page 3.
Section 582-210-702, Issue 2, Page 85.

REFERENCES: None

TCN INDEX CLASSIFICATION: 40 EB 30

W.E. DOCUMENTS AFFECTED: BSRS 456.184 Supplemental
BSRS 456.193 Standard
RS 581.40 Section B-3

W.E. METHODS: This TCN is to be implemented for Standard & Supplemental Repair. All stiff belts shall be disposed of locally.