

21D4 CENTRAL OFFICE SPLICE CASE

DESCRIPTION AND INSTALLATION

1. GENERAL

1.001 This addendum supplements Section 633-560-205, Issue 1. Place this pink sheet ahead of Page 1 of the section.

1.002 This addendum is issued to add precautions on the use of B sealing tape or B sealing cord.

2. CHANGES

2.001 Add the following precautions to the section to ensure a reliable seal in splice closures during cold weather.

(a) Using B cleaning fluid, remove any residue from cable sheath at B sealing tape collar locations.

(b) Scuff the cleaned cable sheath around the entire circumference of the cable. ***Do not scuff the sheath longitudinally as this could produce leak channels.***

(c) Do not heat the B sealing tape or cord directly in the airflow of a heater or blower. This reduces the adhesion of the tape to the cable sheath. If heating is required, place the B sealing tape or cord in a warm place prior to use.

(d) Ensure that the level of the B sealing tape buildup between the sealing washers is ***fully flush or slightly overflush with the sealing washer.***

NOTICE

Not for use or disclosure outside the
Bell System except under written agreement